



Stanceflex ESK+ 239149




1 Static Alignment Guide

Walking trials





Fully extend limb to access the adjuster. Rotate the SPRING STACK ADJUSTER to achieve the required stability for the individual user. Note: Audible clicks should be heard upon adjustment, and the adjuster is self locking. Tighten the SPRING STACK to reduce stability. Release the SPRING STACK to increase stability - See above diagram.

If required, the adjuster may be reset to the factory setting. This can be achieved by reducing stability by six audible clicks from the maximum setting.




2 Changing Flexion Rubbers







3 Front Stop adjustment - Adjustable Trunnion

As fitted to the PSPC and Servo PSPC







The stop pads mounted in the chassis and side plate are required to support ML loading. Simultaneous full contact between the stops and the shin is NOT required.

Withdraw trunnion clamp screw and apply LOCTITE 222 to thread, re-assemble and tighten.

*UNDER NO CIRCUMSTANCES MUST THE PISTON ROD WITNESS LINE BE VISIBLE BELOW THE TRUNNION

Servo PSPC
The Servo PSPC should be adjusted as above except
the trunnion should be rotated further, if required,
until the cut-out in the piston rod is posterior.

Front Stop adjustment - Non-Adjustable Trunnion

[As fitted to the IP+ and Hydraulic Cylinders]

No adjustment is necessary when using these cylinders. They require the front stop to be fully tightened as shown in Stage 1.

4 Maintenance

To maintain optimum performance, a periodic inspection for unacceptable noise, play and stability is recommended. The period between inspections is determined by factors such as the activity of the user, frequency of usage and the stability setting of the knee.

At these inspections:

Check and replace front stop if necessary (see Section 5). Dis-assemble, clean and re-assemble as shown on pages 7 & 8.


As a guide, if the setting is 6 clicks or above and the user averages 600,000 steps per annum, an annual inspection is recommended.

If the stability setting is less than 6 clicks and/or the user averages fewer than the average number of steps, the period inbetween inspections may be longer.


The use of a Limb Activity Monitor is recommended to determine step count.

Adjustment and maintenance must be carried out by competent, trained personnel. If in doubt contact Blatchford Products Limited.


5 Changing front stop buffer




When fitting a new front stop, always re-adjust, and if applicable check length of cylinder if fitted with an adjustable trunnion.
See page 4




Removing ESK+ mechanism




















7 Replacement of ESK+ mechanism



underside view of chassis

Distributor/Distributeur/Händler/Distributore/Distribuidor

Head Office

Chas A Blatchford & Sons Ltd Lister Road Basingstoke Hampshire RG22 4AH United Kingdom

Tel: +44 (0) 1256 316600 Fax: +44 (0) 1256 316617 Email: sales@blatchford.co.uk www.endolite.co.uk

Customer Services UK

Prosthetic and Orthotic Products
11 Atlas Way
Atlas North
Sheffield
S4 7QQ
United Kingdom
Tel: +44 (0) 114 263 7900

Fax: +44 (0) 114 263 7901 Email: sales@blatchford.co.uk

www.endolite.co.uk

endolite North America

1031 Byers Road Miamisburg Ohio 45342 USA Tel: 800.548.3534

Fax: 800.929.3636
Email: info@endolite.com

endolite Germany

Endolite Deutschland GmbH Holzstr. 5 95336 Mainleus GERMANY Tel: +49 9229 9737 001

Tel: +49 9229 9737 001 Fax: +49 9229 9737 006 Email: info@endolite.de www.endolite.de

endolite France

Parc d'Activités de l'Aéroport, 125 Impasse Jean-Baptiste Say 34470 PEROLS FRANCE

Tel: 00 33 (0) 467 820 820 Fax: 00 33 (0) 467 073 630 Email: contact@endolite.fr

www.endolite.fr

endolite India Ltd

A4 Naraina Industrial Area Phase - 1 New Delhi INDIA – 110028 Tel: 91 11 45689955 Fax: 91 11 25891543 Email: endolite@vsnl.com

www.endoliteindia.com

CE